

Expires	ML#		
	ML1502	Ottawa County Road Commission	OK
	ML1505	J&D Investors LLC	
	ML1501	Grand Rapids Gravel/DeWent	OK
	ML1503	Boynon Gravel	OK
	ML1504	Huizenga Gravel Company/Land LLC	OK
6/30/2021	ML1601	DeWent Gravel	OK
6/30/2018	ML1801	Poortenga Properties	OK
6/30/2019	ML1401	Cedar Valley Associates, Inc.	OK

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

Inspection Report Date 11/7/19

**Location:** 9301 12TH AVE, P.P. # 70-14-02-100-004

**Mineral Mining License Number:** PML1501 – old 1004-Grand Rapids Gravel/DeWent

**Comments:** The Code Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

11/7/19: Mining as required: R

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

Inspection Report Date 1/7/19

**Location:** 1551 TAYLOR ST, P.P. # 70-14-02-300-005

**Mineral Mining License Number:** PML1502 – old 1001-Ottawa County Road  
Commission

**Comments:** The Code Enforcement Officer conducted a site inspection at the above  
mining location and has noted the following:

1/7/19: Mining as per D: 22

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

Inspection Report Date 1/7/19

**Location:** 9400 12TH AVE, P.P. # 70-14-02-200-006

**Mineral Mining License Number:** PML1503 – old 1005-Boynton Gravel

**Comments:** The Code Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

No active mining  
Site complies  
RJS

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

**Inspection Report Date** 1/3/19

**Location:** 1861 FILLMORE ST, P.P. # 70-14-03-200-002

**Mineral Mining License Number:** ML1504 – old 1006-Huizinga Gravel

**Comments:** The Code Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

*Operate as required. Pd*

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

**Inspection Report Date** 1/7/19

**Location:** 6610 40TH AVE, P.P. # 70-14-20-300-054

**Mineral Mining License Number:** PML1505 (old-1002) - John Koetje, J & D Investors

**Comments:** The Code Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

No mining equipment or activity on site  
Piles of top soil within development  
Most of area being developed. RD

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

**Inspection Report Date** 11/7/19

**Location:** 1601 CHICAGO DR, P.P. # 70-14-23-100-028

**Mineral Mining License Number:** ML1601-DeWent Gravel

**Comments:** The Code Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

*Nothing was required. RJ*

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

**Inspection Report Date** 1/7/19

**Location:** 2581 Port Sheldon, P.P. # 70-14-21-400-100 and 21-440-004

**Mineral Mining License Number:** PML1801 – old 1303-Poortenga Properties

**Comments:** The Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

No active mining

Top soil storage piles still in place

No grading (R)

**Georgetown Charter Township  
Mineral Mining**

1515 Baldwin Street, P.O. Box 769  
Jenison, MI 49429-0769

Inspection Report Date 1/3/19

**Location:** 2511 Fillmore and 9250 28<sup>th</sup> Ave. P.P. # 70-14-04-200-021

**Mineral Mining License Number:** PML1401-Cedar Valley Associates

**Comments:** The Code Enforcement Officer conducted a site inspection at the above mining location and has noted the following:

Area is being mined & copies with plans.

However there is currently no equipment on the site.

RN